

ROLAND MDX-650 MILLING TUTORIAL

**Assembled by UCO Engineering Physics Majors - Justin Hawkins, Dan
Reser, and Michael Potts**

Table of Contents

1.1 Opening .igs File With Modela Player 4.....	3
1.2 Setting Origin	3
1.3 Setting Orientation.....	3
1.4 Number of Cutting Surfaces.....	4
1.5 Format Model.....	5
1.6 Selecting the Material.....	6
1.7 Creating a New Process.....	7
1.8 Working with the Roland Milling Machine.	11
1.9 Select Cutting Position Setup as shown with the arrow.	19
1.10 Cut Preview:	21
1.11 Use the Copy Process button as shown below.	22
1.12 Sending the Cut Command.....	23
1.13 Select New Process to creating the finish processes.	24
1.14 Copy Processes.....	26

1.1 Opening .igs File With Modela Player 4

Start Modela Player 4 and open the saved SolidWorks *.igs file. Save the new Modela 4 *.mpj file (see Fig. 1-1).




Fig. 1- 1

1.2 Setting Origin

Reorient the part if necessary and set the origin under the Model section.

1.3 Setting Orientation

Proceed to Model tab as shown (see Fig. 1-2, 1-3, & 1-4).




Fig. 1- 2




Fig. 1- 3




Fig. 1- 4

1.4 Number of Cutting Surfaces

Set the number of cutting surfaces. With this orientation two cutting faces will cut the entire part (see Fig. 1-5).




Fig. 1- 5

1.5 Format Model

Format the Modeling Form as shown (Fig. 1-6, 1-7, & 1-8).




Fig. 1- 6

Change the margin to 0.25in as shown below (Fig. 1-7)




Fig. 1- 7

Set overlap as shown below (Fig. 1-8)




Fig. 1- 8

1.6 Selecting the Material

It's important to select proper material. Use the drop down box to select the type (Figure 1-9).




Fig. 1- 9

1.7 Creating a New Process

Refer to figure 1-10.




Fig. 1- 10

Select
Roughing




Fig. 1- 11




Fig. 1- 12




Fig. 1- 13




Fig. 1- 14




Fig. 1- 15

Do not change the values of the tool.
This could result in damage to the tool of mill (Fig. 1-16)




Fig. 1- 16





Fig. 1- 17

1.8 Working with the Roland Milling Machine.

If the mill is not turned on, switch the master power switch on as shown. The switch is located on the right side of the mill.



Turn on
master power
switch

Fig. 1- 18

This is a picture of the user interface of the Roland Mill. All operations are done from this interface.

Note: The large red button is the emergency halt button. Remember it is always better to hit this button then to break some part of the machine!

Navigation dial

Emergency halt button



Fig. 1- 19

Press *Enter* on the first screen to select RML-1 (Roland Machine Language)

Enter button



Fig. 1- 20

Rotate the round navigation dial to scroll through the mill options. If the screen is displaying the coordinates of the tool press *Exit* once to view the option menu. This is always the procedure if one wishes to enter the option menu.

Once in the *Options* menu, scroll down to option 13 ATC (Automatic Tool Changer), as shown below, and press *Enter*.



Fig. 1- 21

Press Enter once again for 13-1 Tool Select



Fig. 1- 22

Press *Enter* once again for option 13-1-1 Tool_1. A different tool may be selected if desired. Choose the tool that will be easiest to align the center point.



Fig. 1- 23

After selecting the tool the Mill will retrieve the tool then move to the position shown below.




Fig. 1- 24

The Roland Mill may not be set at zero on the fourth axis (Rotary Axis). Return back to the *Options* menu and select Option 12 *Rotary Control*.

Press *Enter*



Fig. 1- 25

Press *Enter* to select *Rotate*. Turn the knob to zero degrees then press *Enter*.



Fig. 1- 26

Use the controls seen below to move the tool and material to the marked center point. Moving the material and tool is intuitive. Forward, Back, Right, Left, +Z(up),-Z(down)




Fig. 1- 27

Once near the center begin lowering the tool down (-Z). Stop well before touching the material (0.5 to 0.25")




Fig. 1- 28

Place a piece of paper on top of the material. Use the round wheel to lower the tool tip down to the paper (rotate clockwise to lower). Lower the tool until the paper is just barely resisted to motion. Remove the paper then turn the knob just a bit more until it is just above the material.




Fig. 1- 29

At this point make the last adjustment to get the tip centered.





Fig. 1- 30

The screen now displays the coordinates of the tool. Move on to step 2.10. These numbers entered into the computer.



Fig. 1- 31

1.9 Select Cutting Position Setup as shown with the arrow.



Click to go to
*Cutting
Position
Setup*

Fig. 1- 32

This screen is asking for the tool location. Refer back to the mill display and enter in the coordinates shown.




Fig. 1- 33

Measure the physical size of the material then enter the numbers into the workspace size.





Fig. 1- 34

Leave this setting at the default distance.




Leave default height and click *Next*

Fig. 1- 35

1.10 Cut Preview:

Select *Cut Preview* to view the simulated part as shown by the arrow. This step is not mandatory if the cut lines as seen below look correct.



Click *Cut Preview* button

Fig. 1- 36




Fig. 1- 37

1.11 Use the Copy Process button as shown below.

This generates a second instance of the first cutting process. Open the copied tree and click on top surface. Change this to *Bottom*. Now both processes have been created. New cutting lines will have to be generated for the bottom. Select *Tool Path* just to the left of the *Copy* button.




Fig. 1- 38

1.12 Sending the Cut Command

Use the *Cut* button to send the process to the mill. The cut button is once again shown with a red arrow




Fig. 1- 39

Press *OK* three times to send the operations to the mill.




Fig. 1- 40

Please watch the mill at this point and be ready to press the emergency halt button if needed.

1.13 Select New Process to creating the finish processes.




Fig. 1- 41






Fig. 1- 42



Select *Tool* and click *Next*

Fig. 1- 43



Leave default *Process Name* and click *Finish*

Fig. 1- 44

A preview of the scan lines is automatically generated (Fig. 1-45).




Fig. 1- 45

1.14 Copy Processes

Once again select *Copy Processes*. Then also switch the Top Surface to Bottom once again.




Fig. 1- 46

Make sure that the rough cut commands are not selected. Use the *Cutting/No Cutting* button to deselect those commands




Fig. 1- 47

Press cut once again to start the mill on the final pass.