






Copyright © 2006 Roland DG Corporation
Copyright © 2006 REAL FACTORY INC. Copyright © 2006 GRAPHIC PRODUCTS INC.


Copyright © 2006 REAL FACTORY INC. Copyright © 2006 GRAPHIC PRODUCTS INC.


JWX-30 SRP Player CAM Software



File - Preferences








NOTES:

You can change your preferences, color scheme, machine and accessories in this section.




File – Preferences – Advanced Tab





- •For software versions 1.15 and greater, there is an advanced tab that will allow you to disable certain safety features for advanced users.
- •Please be very familiar with the machine and any accessory before disabling these restrictions.
- •Failure to do so may cause a crash.



Options







NOTES:


My Tool: Select what tools you have available. For JWX-30, the ZEC-J3015 and CAP-LN-EBD tools are used.

Add/Remove Tool: Add or remove additional tools than already installed.

Surfacing: Surfaces work material using available tools.



JewelStudio Software




NOTES:

•If using JewelStudio and SRP Player.




JewelStudio Software



- •Click on the CAM tab.
- •Click on the CAM Export button.



JewelStudio Software




NOTES:

•Click on Select Objects and select objects.



JewelStudio Software




NOTES:

•Right click mouse or press Enter on the keyboard.




JewelStudio Software




- •Select resolution desired.
- •High or Medium work best.



JewelStudio Software




- •Select clamp to be used.
- •Click ok.
- •Make sure that the Set origin to center of model is checked OFF.








Main Screen



- •Start screen. Note you can't proceed until Step 1 is completed.
- •Red line demonstrates rotary axis rotation axis.



Step 1




- •Import part by clicking on Open or dragging part onto screen.
 - •You can import .3dm, .igs, .stl, or 3D .dxf files.
- •A window will appear asking what type of fixture to use.

 Please see JWX-30 setup documents for information on what fixture to use for your application.




Step 1



- Once the part is imported, it should be oriented properly for that fixture.
- •Click on 2 Type of Milling.




Step 2



- •All options on this page will be automatically selected and set up specifically for the fixture selected.
- •Click on 3 Create Tool Path to continue.




Step 3



- Material will automatically be selected to Modeling Wax.
- •The material size will default to the fixture selected. If your wax thickness is different that the thickness stated, please adjust accordingly.
 - •For example, the 2 common thicknesses of material are 16mm and 11mm for this fixture.
- •Click Create Tool Path to process toolpath.
- •Click on Step 4 when finished.




Step 4



- You can view what the sample part will look like with selected tooling by clicking on Preview Cutting.
- •You can view an estimated cutting time.
- •Click on Step 5 when finished.



Step 5




NOTES:

Click on Start Cutting to starting the cutting process.



Back to Step 3



NOTES:


If you would like to make changes to your program, click on Step 3.



Step 3 Modifications

 \blacksquare

© ×




Create Tool Path

NOTES:

- •Click on Edit.
- •You can view and edit your processes as desired.
- •Roughing process quickly removes material leaving a rough finish, usually with a larger tool.
- •Finishing process cleans up the part to its final shape.



😚 Create Tool Path





Edit...



Step 3 Modifications








- Select Roughing process
- Select Top Surface and click on + to view options.
- You can rename the process
- •You can change its orientation and angle if available.
- •Click on Apply when finished.




Step 3 Modifications




- •The cutting depth can be modified if desired by selecting Partial.
- Enter a value or drag the red line to the desired depth.
- •Click on Apply when finished.



Step 3 Modifications








- •You can select available Tool.
- •You can modify available process to desired process if available.
- You can modify recommended feed rates if desired.
- •Click on Apply when finished.




Step 3 Modifications

CAP-LN-EBD (1.0mm Ball) Used for Roughing

ZEC-J3015 (0.1mm Conical) Used for Finishing






- •Cutting parameters can be changed if desired.
- •Click on Apply and Close when finished.
 - •Feed Rate is the speed the tool is moving.
 - Spindle speed is how fast the tool is spinning.
 - •Cutting in amount is the depth of cut for that tool.
 - •The Path interval is the distance between tool passes. Finishing passes are usually much smaller than roughing passes.
 - •Finish margin is the amount of material left on the model after that process has finished.




Step 3 Modifications



- •Click on Create Tool Path to generate the tool path.
- •Click on Step 4 when finished.



Step 5



NOTES:

•Click on Start Cutting to starting the cutting process.