



Copyright © 2006 Roland DG Corporation
Copyright © 2006 REAL FACTORY INC. Copyright © 2006 GRAPHIC PRODUCTS INC.

Copyright © 2006 Reland DG Corporation Copyright © 2006 GRAPHIC PRODUCTS INC.

SRP Player CAM Software



Installing SRP Player Software






- •Place SRP Player CD into computer and an install window will open.
- •Click on "Install" to begin software installation.





Installing SRP Player Software












- •Install Shield Wizard will start up, click on "Next".
- •Read software license agreement and click on "Yes"
- •Click "Next" to accept default destination folder. (Recommended)
- •Click "Next" to accept default program folder name and continue software installation. (Recommended)



Installing SRP Player Software





- •Click on "Finish" to complete software installation.
- •Go to Windows Start Menu and click on SRP Player, right click over SRP Player, select "Send To" then "Desktop (create shortcut)"
- •This will create a shortcut on your desktop.







Installing SRP Player Software















- •Click on SRP Player shortcut to launch software.
- •When you start the software for the first time or update the software, the initialization screen will appear. Click on "Next" to begin initialization.
- •Software will look for installed machine.
- •Select your machine.




Installing SRP Player Software













Check the box for the tool you're using.	Tool Specifications			
fit is not listed, use [New] to register it.	Tool Name:	1/8" Square		
1mm Conical		Tool <u>T</u> ype: <u>M</u> aterial:	Straight	
☐ ○ 1/32" Ball ○ 1/16" Ball			Cemented carbide	
✓ N 1/8" Ball	() ()	Flute Diameter [d]:	3.18	mm
✓ 0 1/4" Ball	V/	Flute Length []:	9.48	mm
☐ ○ 1/16" Square		Corner Radius [r]:		mm
 ✓ 1/8" Square ✓ 1/4" Square 	Fa ²	Blade Width	0.00	mm
☐ O ZEC-J3015	1	[w]: Blade Angle		deg
New Copy Delete		[a]	Regis	


- •Verify machine and installed options then click "Next".
- •Software will indicate machine selected and options selected. Click "Next".
- •Select units desired. Click "Next"
- •Select tools in inventory then click "Next".
- •Click on "Finish" to complete the software initialization.






File - Preferences









NOTES:

You can change your preferences, color scheme, verify machine and accessories by selecting File then Preferences.






File - Preferences - Advanced Tab





- •For software versions 1.15 and greater, there is an advanced tab that will allow you to disable certain safety features for advanced users.
- •Please be very familiar with the machine and any accessory before disabling these restrictions.
- •Failure to do so may cause a crash.




Options










NOTES:

My Tool: Select what tools you have available


Add/Remove Tool: Add or remove additional tools than already installed.

Surfacing: Surfaces work material using available tools.






Main Screen



- •Start screen. Note you can't proceed until Step 1 is completed.
- •Red line demonstrates rotary axis rotation axis if available.




Step 1



- •Import part by clicking on Open or dragging part onto screen.
- Confirm size of part.
 - •Modify if desired.
- •Check orientation of part.
- •Click on Step 2 when finished.




Step 2



- •You select what type of part you will be cutting by selecting the appropriate options.
- •Click on question mark for more information.
- •Click on Step 3 when finished.




Step 3



- •Select material from pull down list.
- •Enter material size.
 - •Must be greater than values in parenthesis.
- •Click Create Tool Path to process toolpath.
- •Click on Step 4 when finished.




Step 4



- You can view what the sample part will look like with selected tooling by clicking on Preview Cutting.
- •You can view an estimated cutting time.
- •Click on Step 5 when finished.



Step 5




NOTES:

Click on Start Cutting to starting the cutting process.



Back to Step 3




NOTES:


If you would like to make changes to your program, click on Step 3.



Step 3 Modifications










- •Click on Edit.
- You can view and edit your processes as desired.
- •Roughing process quickly removes material leaving a rough finish, usually with a larger tool.
- •Finishing process cleans up the part to its final shape.



Step 3 Modifications








- Select Roughing process
- Select Top Surface and click on + to view options.
- You can rename the process
- •You can change its orientation and angle if available.
- •Click on Apply when finished.




Step 3 Modifications



- •Under Modeling Form, you can change the margins of the part.
- •Click on Add a margin
- Click on Automatically
- You only need to add a margin above and below the part.
- •You don't want to add a margin to the left or right.
- •Once finished click Apply.



Step 3 Modifications




NOTES:

•Completed margin modifications.




Step 3 Modifications



- •You can modify the Cutting Area if desired by selecting Partial.
- You can enter values to specify the cutting area or drag the red box to the desired area.
- •Click on Apply when finished.




Step 3 Modifications





- •The cutting depth can be modified by selecting Partial.
- Enter a value or drag the red line to the desired depth.
- •Click on Apply when finished.




Step 3 Modifications










- •You can select available Tool.
- •You can modify available process to desired process if available.
- You can modify recommended feed rates if desired.
- •Click on Apply when finished.
- •Click on Close when all modifications have been completed.




Step 3 Modifications



- •Cutting parameters can be changed if desired.
- •Click on Apply and Close when finished.
- •Feed Rate is the speed the tool is moving.
- •Spindle speed is how fast the tool is spinning.
- •Cutting in amount is the depth of cut for that tool.
- •The Path interval is the distance between tool passes. Finishing passes are usually much smaller than roughing passes.



Step 3 Modifications





NOTES:

•Finish margin is the amount of material left on the model after that process has finished



Step 3 Advanced Modifications





- •Let's make some advanced modifications.
- •The part in questions has some holes that can't be milled from the top or the bottom.




- •We can turn the part at angle to mill the holes.
- •We simply add a new process, usually finishing.
- •Change the angle to 45 degrees and click apply to change the part.




Step 3 Advanced Modifications



Wireframe View






- •As we only want to cut the holes, lets change the cutting area to cut only the holes.
- •Click on Partial and simply drag the box to an area outside the tools.
- •Click Apply when finished.
- •For the depth, click on the start cutting line and bring it so that it is right below the depth of the hole.
- •Bring the stop cutting line just below the holes so that the tool doesn't waste time cutting too deep.
- •You may want to change the view to Wireframe view to view the holes better.
- •Click Apply when finished.



Step 3 Advanced Modifications




- •To cut the other side, add another new finishing process.
- •Change the angle to 315 degrees and click Apply.




Step 3 Advanced Modifications



Wireframe View






- •Again, as we only want to cut the holes, lets change the cutting area to cut only the holes.
- •Click on Partial and simply drag the box to an area outside the tools.
- •Click Apply when finished.
- •For the depth, click on the start cutting line and bring it so that it is right below the depth of the hole.
- •Bring the stop cutting line just below the holes so that the tool doesn't waste time cutting too deep.
- •You may want to change the view to Wireframe view to view the holes better.
- •Click Apply when finished.
- •Click Close when finished editing.




Step 3 Advanced Modifications



- •Click on Create Tool Path to generate the tool path.
- •Click on Step 4 when finished.




Step 4



- You can view what the sample part will look like with selected tooling by clicking on Preview Cutting.
- •You can view an estimated cutting time.
- •Click on Step 5 when finished.




Step 5



NOTES:

•If you have an Automatic Tool Changer, you can Edit Magazine to specify tool location.



•Click on Start Cutting to starting the cutting process.