Roland

Roland ColorChoice Update

We have found the following problem in RCC4.1A for inkjet and also RCC4.1A for ColorCAMM.

Symptom :
Installation of RCC4.1A to MacOS upto ver 8.6 will result in either a Type Error 1 or a computer lock-up. The problem happens only with RCC4.1A and MacOS up to ver 8.6. There is no problem with RCC4.1 or RCC4.1B and MacOS 9.0 or later.

Fix:
The problem has been corrected with RCC4.1B. Please contact your dealer to receive an upgrade.

Serial Number :
Machines with the following serial numbers were shipped with RCC4.1A.
FJ-600 : ZO40135 ~ ZO50224
FJ-500/400 : none
CJ-500 : ZO42070 ~ ZO52139
CJ-400 : ZO50240 ~ ZO60244
FJ-52 : ZO40630 ~ ZO50644
FJ-42 : ZO40205 ~ ZO50219
PC-600 : ZO41110 ~ ZO51350

We are sorry for the inconvenience caused by this problem.