JWX-30 Milling Machine Specifications

GENERAL

Cuttable Material:

X, Y, and Z Operation Strokes X, Y, and Z:

Connectivity

Modeling wax

305 x 205 x 100 mm (12 x 8.1 x 3.9 in.)

USB 1.1

POWER REQUIREMENTS

Voltage and Frequency AC 100 to 120 V/220 to $240 \text{ V} \pm 10\%$, 50/60 Hz

> (overvoltage category II, IEC 60664-1) 2.8 A (100 to 120 V)/1.2 A (220 to 240 V)

275 W

Required Power Capacity Power Consumption

OTHER

Dimensions Height x width x depth: 606 x 656 x 557 mm

(23.9 x 25.9 x 22 in.)

Weight 47 kg (104 lb)

Environmental Operating environment: Temperature of 5 to

> 40°C (41 to 104 °F), 35 to 80% relative humidity (no condensation) Ambient pollution degree: 3 (as specified by IEC

60664-1)

Accessories Power cord, Handy panel, Tools for modeling

(ball end mill, diameter 3.175mm /conical

end mill, diameter 3.175 mm), collet (diameter 3.175 mm), detection pin,

hexagonal screwdriver, hexagonal wrench, cap screws (10), spanner (10 mm, 17mm), modeling wax, clamp holder, square clamp (large), square clamp (small), swivel clamp, tube clamp, dust tray, blower fan, User's Manual (this document), SRP Player

Installation and Setup Guide, SRP Player CD-ROM, Roland Software Package CD-ROM,

Roland JewelStudio DVD-ROM

SYSTEM REQUIREMENTS

Model preinstalled with Windows Vista, XP, Computer

> 2000, or upgraded computer originally preinstalled with Windows 2000 or later. Pentium, Celeron, or higher Processor.

1Gb Disk Space

512 Mb RAM (1Gb or more recommended)

IntelliMouse recommended

Use a shielded cable up to 3 meters (10 ft) in

length.

USB Cable