



What's new in SR1

What's New in Service Release 1 (16-Dec-2009):

New features:

- The isocurve density can be specified by object.
- Added filter by name in the style list from the object insertion dialogs.
- When entering the roof slope, the ratio format can be used (i.e. "1:2").
- Added template in feet.

Fixed bugs:

- Fixed an error when measuring surfaces in rooms with columns that collided.
- The licence agreement in the installer did not display correctly.
- A line was cut in the About dialog box.
- Stair flights that did not have 0 elevation were not shown correctly.
- Stairs were not correctly copied.
- Fixed a bug with the plan representation of walls with NURBS shape.
- When opening a drawing with extended walls, sometimes the walls were not extended.
- vaWallSetPath command no longer accepts closed curves.
- VisualARQ didn't load correctly in Windows 2000.
- Fixed a crash when importing a drawing with VisualARQ objects
- Fixed a crash when enabling the texture mapping display widget.
- Fixed a crash when working with layers whose name started with a symbol.
- Fixed a crash when opening a drawing edited from a Rhino without VisualARQ, where the blocks or text or dimension styles were deleted.

Know bugs and limitations:

- VisualARQ objects are ignored when they are inside a block.